

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including USACE Erosion Survey**

**Sacramento River Basin**

<b>NA0004</b>	Overall LMA Rating	Total LMA Miles				
<b>Marysville Levee Commission</b>	<b>A</b>	<b>11.38</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	1.10		1.10	9.67%		
Encroachments					0.01	0.01
<i>LMA Totals:</i>	1.10	0.00	1.10	9.67%	0.01	0.01
<b>Unit No. 01 Simmerly Slough</b>	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>3.25</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
<b>Unit No. 02 Feather River</b>	Overall Unit Rating	Total Unit Miles				
	<b>U</b>	<b>1.27</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.43		0.43	33.86%		
<i>Unit Totals:</i>	0.43	0.00	0.43	33.86%	0.00	0.00
<b>Unit No. 03 Yuba River</b>	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>6.86</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.67		0.67	9.77%		
Encroachments					0.01	0.01
<i>Unit Totals:</i>	0.67	0.00	0.67	9.77%	0.01	0.01

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2010 Levee Inspection Results**

**Marysville Levee Commission**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2010 Levee Inspection Results**

**Marysville Levee Commission**

Waterway			Bank	Unit Miles
Unit No. 01 Simmerly Slough			Left	3.25
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/16/2010		9/28/2010	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Frank Miller Marysville Levee District		Frank Miller Marysville Levee District	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Simmerly Slough				Left	3.25	10/12/2010 10/12/2010	Clay Thomas	

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	2.50	2.50	Earthen Levee	Crown Surface / Depressions / Rutting	LS	A	Inspector Comments: This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1_2010_a_0036). Reinspection on 12/9/10 verifies that repairs were made as indicated in the 11/22/10 letter from the City.	39.164965 ° -121.572142 °	39.164965 ° -121.572142 °	4 Y
2	3.19	3.19	Earthen Levee	Cracking	CR	A	Inspector Comments: This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1_2010_a_0028). Reinspection on 12/9/10 verifies that repairs were made as indicated in the 11/22/10 letter from the City.	39.163941 ° -121.560452 °	39.163941 ° -121.560452 °	5 Y
3	3.23	3.23	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	39.163589 ° -121.559494 °	39.163589 ° -121.559494 °	1 Y
4	3.23	3.23	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	39.163589 ° -121.559494 °	39.163589 ° -121.559494 °	2 Y
5	3.24	3.24	Earthen Levee	Slope Stability	LS	A	Repair slope instability. Inspector Comments: This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1_2010_a_009). Reinspection on 12/9/10 verifies that repairs were made as indicated in the 11/22/10 letter from the City.	39.163589 ° -121.559494 °	39.163589 ° -121.559494 °	3 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**


**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.25	10/12/2010 10/12/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	2.50
End Levee Mile	2.50
Location	Land Side
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1_2010_a_0036). Reinspect on 12/9/10 verifies that repairs were made as indicated in the 11/22/10 letter from the City.	
cathom_f_20101209_166.jpg	



Levee Mile Report Line	1
Start Levee Mile	2.50
End Levee Mile	2.50
Location	Land Side
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1_2010_a_0036). Reinspect on 12/9/10 verifies that repairs were made as indicated in the 11/22/10 letter from the City.	
cathom_f_20101209_167.jpg	



Levee Mile Report Line	1
Start Levee Mile	2.50
End Levee Mile	2.50
Location	Land Side
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1_2010_a_0036). Reinspect on 12/9/10 verifies that repairs were made as indicated in the 11/22/10 letter from the City.	
cathom_f_20101209_168.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated	C : Corrected W : Watch/Monitor
--	--	--	------------------------------------



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.25	10/12/2010 10/12/2010	Clay Thomas

Levee Mile Report Line	2
Start Levee Mile	3.19
End Levee Mile	3.19
Location	Crown
Category	Earthen Levee
Item	Cracking

This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1\_2010\_a\_0028). Reinspect on 12/9/10 verifies that repairs were made as indicated in the 11/22/10 letter from the City.

cathom\_f\_20101209\_169.jpg



Levee Mile Report Line	2
Start Levee Mile	3.19
End Levee Mile	3.19
Location	Crown
Category	Earthen Levee
Item	Cracking

This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1\_2010\_a\_0028). Reinspect on 12/9/10 verifies that repairs were made as indicated in the 11/22/10 letter from the City.

cathom\_f\_20101209\_170.jpg



Levee Mile Report Line	3
Start Levee Mile	3.23
End Levee Mile	3.23
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 3.23, land side vegetation, looking up stream.

cathom\_f\_20101019\_160.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.25	10/12/2010 10/12/2010	Clay Thomas

Levee Mile Report Line	4
Start Levee Mile	3.23
End Levee Mile	3.23
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Levee mile 3.23, water side vegetation, looking up stream.	
cathom_f_20101019_161.jpg	



Levee Mile Report Line	5
Start Levee Mile	3.24
End Levee Mile	3.24
Location	Land Side
Category	Earthen Levee
Item	Slope Stability
This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1_2010_a_009). Reinspect on 12/9/10 verifies that repairs	
cathom_f_20101019_162.jpg	



Levee Mile Report Line	5
Start Levee Mile	3.24
End Levee Mile	3.24
Location	Land Side
Category	Earthen Levee
Item	Slope Stability
This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1_2010_a_009). Reinspect on 12/9/10 verifies that repairs	
cathom_f_20101019_163.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated	C : Corrected W : Watch/Monitor
--	--	--	------------------------------------



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.25	10/12/2010 10/12/2010	Clay Thomas

Levee Mile Report Line	5
Start Levee Mile	3.24
End Levee Mile	3.24
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1\_2010\_a\_009). Reinspect on 12/9/10 verifies that repairs

cathom\_f\_20101209\_164.jpg



Levee Mile Report Line	5
Start Levee Mile	3.24
End Levee Mile	3.24
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

This item was identified with an Unacceptable rating in the USACE PI report for the City of Marysville 1 Levee System (MRY1\_2010\_a\_009). Reinspect on 12/9/10 verifies that repairs

cathom\_f\_20101209\_165.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated



**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2010 Levee Inspection Results**

**Marysville Levee Commission**

Waterway			Bank	Unit Miles
Unit No. 02 Feather River			Left	1.27
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	3/16/2010		9/28/2010	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Frank Miller		Frank Miller	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River						Left	1.27	10/12/2010 10/12/2010	Clay Thomas

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	39.149371 ° -121.601100 °	39.149371 ° -121.601100 °	2 Y
2	0.02	0.45	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.149371 ° -121.601098 °	39.143275 ° -121.600329 °	1 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.27	10/12/2010 10/12/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Levee mile 0.00, vegetation on water side slope.	
cathom_f_20101019_165.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.02
End Levee Mile	0.45
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Levee mile 0.00, vegetation on land side slope.	
cathom_f_20101019_164.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2010 Levee Inspection Results**

**Marysville Levee Commission**

Waterway			Bank	Unit Miles
Unit No. 03 Yuba River			Right	6.86
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	3/16/2010		9/28/2010	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Frank Miller Marysville Levee District		Frank Miller Marysville Levee District	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway						Bank	Unit Miles	Inspection Start/End		Inspector
Unit No. 03 Yuba River						Right	6.86	10/12/2010 10/12/2010		Clay Thomas
LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.34	0.34	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	39.135172 ° -121.587852 °	39.135172 ° -121.587852 °	2 Y
2	0.34	1.00	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.135172 ° -121.587852 °	39.141738 ° -121.582777 °	1 Y
3	0.35	0.35	Earthen Levee	Encroachments	LS	PO	Landscaping	39.135145 ° -121.587730 °	39.135145 ° -121.587730 °	3
4	0.86	0.86	Earthen Levee	Encroachments	LS	CO	Buildings	39.139843 ° -121.583033 °	39.139843 ° -121.583033 °	4 Y
5	4.36	4.36	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: This is the location of the unacceptable items from the Corps.	39.178863 ° -121.545445 °	39.178863 ° -121.545445 °	6 Y
6	4.36	4.36	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: This is the unacceptable items from the Corps.	39.178863 ° -121.545445 °	39.178863 ° -121.545445 °	7 Y
7	4.90	4.90	Earthen Levee	Vegetation	CR	A	Control annual grass and weeds on the levee slopes and easements.	39.185389 ° -121.539973 °	39.185389 ° -121.539973 °	8 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.86	10/12/2010 10/12/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.34
End Levee Mile	0.34
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 0.34, water side slope.

cathom\_f\_20101019\_168.jpg



Levee Mile Report Line	2
Start Levee Mile	0.34
End Levee Mile	1.00
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 0.34, vegetation looking up stream.

cathom\_f\_20101019\_167.jpg



Levee Mile Report Line	4
Start Levee Mile	0.86
End Levee Mile	0.86
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Building encroaching at land side levee toe.

cathom\_f\_20101019\_166.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.86	10/12/2010 10/12/2010	Clay Thomas

Levee Mile Report Line	5
Start Levee Mile	4.36
End Levee Mile	4.36
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Water side vegetation removed. Levee mile 4.36.

cathom\_f\_20101019\_169.jpg



Levee Mile Report Line	5
Start Levee Mile	4.36
End Levee Mile	4.36
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 4.36, water side tree removed as part of vegetation removal.

cathom\_f\_20101019\_170.jpg



Levee Mile Report Line	6
Start Levee Mile	4.36
End Levee Mile	4.36
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 4.36, land side levee slope vegetation removed. Looking up stream.

cathom\_f\_20101019\_171.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Marysville Levee Commission**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.86	10/12/2010 10/12/2010	Clay Thomas

Levee Mile Report Line	7
Start Levee Mile	4.90
End Levee Mile	4.90
Location	Crown
Category	Earthen Levee
Item	Vegetation
Levee mile 4.90, this is the patrol road.	
cathom_f_20101019_172.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated